





List 2100: 5 Flute, Square End

List 2106: 5 Flute, Corner Radius

List 2102: 5 Flute, Regular Length, Reduced Neck, Square End

List 2108: 5 Flute, Regular Length, Reduced Neck, Corner Radius

	Side Milling		Slotting	
Cutting Speed	200-265 SFM		100-165 SFM	
Depth of Cut	$a_a \leq 1.8D$ $a_r = 0.2D$ 		$a_a \leq 1D$ 	
Mill Dia.	Speed RPM	Feed in/min	Speed RPM	Feed in/min
1/2	1,800	31.9	1,030	10.2
5/8	1,435	25.5	825	8.2
3/4	1,200	25.7	700	8.3
1	900	19.7	515	6.0

1. Use a rigid and precise machine and holder.
2. The above cutting conditions are to be used as general guidelines. Please adjust the speed, feed and cutting depth according to actual cutting conditions.
3. Water soluble coolant is highly recommended.

